



# APS Automotive Enterprises Co.,Ltd.

A2,2ND Floor,Main Building,33 Changhong Road,Modern Logistics Park,Xiamen,China 361006

Tel: 86-592-5619 592 86-592-2620 070 Fax: 86-592-5610884 E-mail: aa@aaps.cn / karl@cps.cn

<http://www.apspart.com>

<http://apsparts.en.alibaba.com/index.html>

| NO. | CAR   | APS NO.       | OEM NO | MODEL & DESCRIPTION | CYL NO. | CYL. DIA | PISTON |                    |                |        | PIN |      | CLIP         | N.W. (KG) |
|-----|-------|---------------|--------|---------------------|---------|----------|--------|--------------------|----------------|--------|-----|------|--------------|-----------|
|     |       |               |        |                     |         |          | LONG   | COMP DIST          | RING           |        | DIA | LONG |              |           |
|     |       |               |        |                     |         |          |        |                    | COMP           | OIL    |     |      |              |           |
| 1   | IVECO | APS 31101     |        | 493                 | 4       | 93       | 96.7   | 58.8-18.4          |                |        | 32  |      |              | 0.8886    |
| 2   | IVECO | APS 31101J    |        | 493                 | 4       | 93       | 96.7   | 58.8-18.4          |                |        | 32  |      |              | 0.8886    |
| 3   | IVECO | APS C-31101J  |        |                     | 4       | 93       | 96.7   | 58.8-18.4<br>-14.2 | 1-1.8<br>1-2.0 | 1-3.0  | 32  | 78.0 | 35.5<br>1.9R | 0.8886    |
| 4   | IVECO | APS 31102/J   |        | 493                 | 4       | 93       | 96.7   | 58.8-17.8<br>-12.9 | 1-1.9<br>1-2.0 | 1-3.0  | 32  | 77.8 | 35.5<br>2.0R | 0.94      |
| 5   | IVECO | APS 31102J/JH |        | 493                 | 4       | 93       | 96.7   | 58.8-17.8<br>-12.9 | 1-1.9<br>1-2.0 | 1-3.0  | 32  | 77.8 | 35.5<br>2.0R | 0.94      |
| 6   | IVECO | APS 31102P    |        | 493                 | 4       | 93       | 96.7   | 58.8-17.8          |                |        | 32  |      |              | 0.94      |
| 7   | IVECO | APS 31102JP   |        | 493                 | 4       | 93       | 96.7   | 58.8-17.8          | 3-2.38         | 2-4.76 | 32  |      |              | 0.94      |
| 8   | IVECO | APS 31103     |        |                     | 4       | 93       | 96.7   | 58.7-18.3          | 1-3.0<br>1-2.0 | 1-3.0  | 32  | 78.0 | 35.5<br>1.8R |           |
| 9   | IVECO | APS 31103J    |        |                     | 4       | 93       | 96.7   | 58.7-18.3          | 1-3.0<br>1-2.0 | 1-3.0  | 32  | 78.0 | 35.5<br>1.8R | 0.956     |
| 10  | IVECO | APS 31104     |        | 493                 | 4       | 93       | 96.7   | 58.8-18.4          | 1-3.0<br>1-2.0 | 1-3.0  | 32  | 78.0 | 35.5<br>2.0R |           |
| 11  | IVECO | APS 31104J    |        | 493                 | 4       | 93       | 96.7   | 58.8-18.4          | 1-3.0<br>1-2.0 | 1-3.0  | 32  | 78.0 | 35.5<br>2.0R |           |
| 12  | IVECO | APS 31105     |        | 8035.06.306         | 4       | 100      | 108.6  | 65.1-22.6          | 2-2.5          | 1-5.5  | 38  | 85   | 42           | 2.0R      |
| 13  | IVECO | APS 31106J    |        |                     | 4       | 94.5     | 87.5   | 58.7-19.4<br>-15.2 | 1-1.4<br>1-2.0 | 1-2.5  | 32  | 71.7 | 35.5<br>2.2R | 0.826     |
| 14  | IVECO | APS 31107     |        |                     | 4       | 100      | 101.1  | 59.6-23.7<br>-13.5 | 2-2.5          | 1-5.5  | 32  | 84   | 35.5<br>1.6R |           |