



APS Automotive Enterprises Co.,Ltd.

A2,2ND Floor,Main Building,33 Changhong Road,Modern Logistics Park,Xiamen,China 361006

Tel: 86-592-5619 592 86-592-2620 070 Fax: 86-592-5610884 E-mail: aa@aaps.cn / karl@cps.cn

<http://www.apspart.com>

<http://apsparts.en.alibaba.com/index.html>

NO.	CAR	APS NO.	OEM NO	MODEL & DESCRIPTION	CYL NO.	CYL. DIA	PISTON				PIN		CLIP	N.W. (KG)
							LONG	COMP DIST	RING		DIA	LONG		
									COMP	OIL				
1	LANDROVER	APS 28001		O.H.V SERISEL 2286cc	4	90.5 3.563"	100.0 3.9371"	58.3 2.2953"	2-1.8	1-4.76	25.4	76.0	27.5 1.2W R25.4	0.65
2	LANDROVER	APS 28002	275820		4	90.475 3.56201"	100.0 3.9371"	58.5 2.30315"	2-1.8	1-4.76	25.4	76.0	27.5 1.2W R25.4	0.58
3	LANDROVER	APS 28002A	10J29		4	90.475 3.56201"	100.0 3.9371"	58.5 2.30315"	2-1.8	1-4.76	25.4	76.0	27.5 1.2W R25.4	0.624
4	LANDROVER	APS 28002B	275820		4	90.475 3.56201"	100.0 3.9371"	58.5 2.30315"	2-1.8	1-4.76	25.4	76.0	27.5 1.2W R25.4	0.574
5	LANDROVER	APS 28003		RA2151	4	90.5 3.563"	99.745 39.27"	57.937 2.281"	2-1.8	1-4.76	25.4	75.79	27.5 1.2W R25.4	0.577
6	LANDROVER	APS 28004			4	90.475 3.56201"	100.0 3.9371"	58.62-6.5 2.3079"-0.256"	3-2.4	2-4.76	30.163	74.0	32.1 1.2W	0.845
7	LANDROVER	APS 28005		TOVER 4.6	8	94	66.4	35.9-5.8	1-1.2 1-1.5	1-3.0	24.0	59.0		0.845