



APS Automotive Enterprise Co.,Ltd.

A2,2ND Floor,Main Building,33 Changhong Road,Modern Logistics Park,Xiamen,China 361006

Tel: 86-592-5619 592 86-592-2620 070 Fax: 86-592-5610884 E-mail: aa@aaps.cn / karl@cps.cn

<http://www.apspart.com> <http://apsparts.en.alibaba.com/index.html> <http://apspart.manufacturer.globalsources.com>

Rear Ladder

NO.	CAR	APS NO.	Item NO.	Picture	Description
1	Mitsubishi	A9802001	P2084A (MS-E049)		
2	Mitsubishi	A9802002	P2197 (MS-E009)		
3	Mitsubishi	A9802003	P0108 (MS-Z010)		
4	Mitsubishi	A9802004	P208 (MS-E062)		
5	Mitsubishi	A9802005	1992-1998 Mitsubishi Pajero V73		Material:304SS FOR: 92-98 Mitsubishi Pajero V73
6	Mitsubishi	A9802006	2001-2004 Mitsubishi Pajero V73		Material:304SS FOR: 01-04 Mitsubishi Pajero V73
7	Toyota	A9802051	HD46 (FJ120-E024) ---350 (280)		

8	Toyota	A9802052	1995-2000 Toyota Land Cruiser FJ70		Material:304SS FOR: 95-02 Toyota Land Cruiser FJ70
9	Toyota	A9802053	1995-2000 Toyota Land Cruiser FJ90		Material:304SS FOR: 95-02 Toyota Land Cruiser FJ90
10	Toyota	A9802054	1998-2003 Toyota Prado FJ100		Material:304SS FOR: 98-03 Toyota Toyota Prado FJ100
11	Toyota	A9802055	2003 Toyota Prado FJ120		Material:304SS FOR: 03 Toyota Prado FJ120
12	Nissan	A9802101	P4047 (NS-E001)		
13	Jeep cherokee	A9802151	P3083 (JP-E009)		
14	Jeep cherokee	A9802152	P3082 (JP-B008)		