



APS Automotive Enterprises Co.,Ltd.

A2,2ND Floor,Main Building,33 Changhong Road,Modern Logistics Park,Xiamen,China 361006

Tel: 86-592-5619 592 86-592-2620 070 Fax: 86-592-5610884 E-mail: aa@aaps.cn / karl@cps.cn

<http://www.apspart.com>

<http://apsparts.en.alibaba.com/index.html>

NO.	CAR	APS NO.	OEM NO	MODEL & DESCRIPTION	CYL NO.	CYL. DIA	PISTON				PIN		CLIP	N.W. (KG)
							LONG	COMP DIST	RING		DIA	LONG		
									COMP	OIL				
1	AUSTIN	APS 25501		MORRIS	4	62.953 2.4785"	65.379 2.574"	33.655- 40.64	3-1.8	1-5/32"	15.875	55.8		0.21
2	AUSTIN	APS 25502	20117	1700cc	4	84.442	73.48	43.51-4.78	2-1.8	1-4.0	20.64	70.28		0.416
3	AUSTIN	APS 25502A	20118	LEYLAND 'O' SERIES SHERPA	4	84.442	72.16	42.19-4.78	2-1.8	1-4.0	20.64	70.28		0.398
4	AUSTIN	APS 25502C	175-9801R		4	84.442	70.8	40.83-2.2	2-1.8	1-4.0	20.64	70.00		0.398
5	AUSTIN	APS 25502CG			4	84.5	70.8	40.83-2.2	2-1.5	1-4.0	20.64	70	*	397.8gr
6	AUSTIN	APS 25503		MAX1 1748cc	4	76.212 3.0005"	59.436 2.340"	35.839-3.505 1.1411"- 0.138"	2-1.6	1-5/32"	20.64	68.5		0.326
7	AUSTIN	APS 25504			4/8	76.212 3.0005"	59.436 2.340"	35.839-6.35 1.1411"- 0.250"	2-1.6	1-5/32"	20.64	68.5		0.302
8	AUSTIN	APS 25505	12A673	MORRIS MINI DELUXE 998cc	4/8	64.592 2.543"	65.354 2.573"	33.68-5.0 1.326"-0.197"	3-1.6	1-1/8"	15.875	55.5	18.5 1.2R	0.189
9	AUSTIN	APS 25506		RP22001	4	62.95 2.4784"	65.8 2.5906	34.057 1.34083"	2-1/16"	1-1/8"	15.875	55.2		0.21
10	AUSTIN	APS 25507		RP22055	4	80.3 3.1615"	61.1 2.4056 "	42.1-3.8 1.6575"- 0.14961"	2-1/16"	1-5/32"	20.64	57.0		0.332
11	AUSTIN	APS 25507A		B series	4	81	61.1	42.1-3.8	2-1.58	1-3.96	20.64	57.0	22.5 1.0W	0.332
12	AUSTIN	APS 25507AQ		B series	4	81	61.1	42.1-3.8	2-1.5	1-4.0	20.64	57.0		
13	AUSTIN	APS 25508		RP22016	4	80.3 3.1615"	77.0 3.0315 "	42.1-6.98 1.6575"- 0.27481"	3-1/16"	1-5/32"	20.64	70.6	22.5 1.0W RTW21	0.39