



APS Automotive Enterprises Co.,Ltd.

A2,2ND Floor,Main Building,33 Changhong Road,Modern Logistics Park,Xiamen,China 361006

Tel: 86-592-5619 592 86-592-2620 070 Fax: 86-592-5610884 E-mail: aa@aaps.cn / karl@cps.cn

<http://www.apspart.com>

<http://apsparts.en.alibaba.com/index.html>

NO.	CAR	APS NO.	OEM NO	MODEL & DESCRIPTION	CYL NO.	CYL. DIA	PISTON				PIN		CLIP	N.W. (KG)
							LONG	COMP DIST	RING		DIA	LONG		
									COMP	OIL				
1	BMW	APS 10101		50cc	2	68.0	70.8	31.6+9.2	2-2.0	1-4.0	20	56.0	23 1.4R	0.235
2	BMW	APS F-31501J		M202	6	80.0	62.4	39.4-2.5	1-3.0 1-1.7	1-3.0	27.0	63.0	30.0*1.7R	
3	BMW	APS F-31502			6	80.0	51.3	33.8-2.0	2-1.5	1-2.0	22.0	51.0	25.0*1.4R	
4	BMW	APS F-31503			6	89.0	71.71	42.8+2.91	1-1.5 1-2.0	1-3.5	22.0	62.0	25.0*1.6R	
5	BMW	APS F-31504			6	84.0	52.6	32.7-2.4 -1.9	2-1.5	1-2.0	22.0	56.0	25.0*1.6R	
6	BMW	APS F-31505		M43 B19	4	85.0	53.9	30.4-4.0	1-1.2 1-1.5	1-2.0	22.0	54.0	25.0*1.4R	
7	BMW	APS F-31506		M52 B28	4	84.0	51.82	31.82	2-1.5	1-2.0	22.0	56.0	25.0*1.6R	