



APS Automotive Enterprises Co.,Ltd.

A2,2ND Floor,Main Building,33 Changhong Road,Modern Logistics Park,Xiamen,China 361006

Tel: 86-592-5619 592 86-592-2620 070 Fax: 86-592-5610884 E-mail: aa@aaps.cn / karl@cps.cn

<http://www.apspart.com>

<http://apsparts.en.alibaba.com/index.html>

NO.	CAR	APS NO.	OEM NO	MODEL & DESCRIPTION	CYL NO.	CYL. DIA	PISTON				PIN		CLIP	N.W. (KG)
							LONG	COMP DIST	RING		DIA	LONG		
									COMP	OIL				
1	BUICK	APS 25301			8	78.581 3 3/32"	109.934 4.3281"	58.313+11.9 34 2.2958"+0.46 98"	2-3/32"	2-3/16"	20.625	68.5		0.434
2	BUICK	APS 25302	12563403	3.0	6/8	89	59.8	39.8-6.6	1-1.2 1-1.5	1-3.0	23	57.0		0.374
3	BUICK	APS 25303			6	89	61.8	39.8-6.6	1-1.2 1-1.5	1-3.0	23	57		
4	BUICK	APS F-25304		V6	6	97.53	65.5	35.5-6.6	2-1.5	1-3.0	23	57.6	26.0*1.6R	
5	BUICK	APS F-25305	H1747	3.8L,V6	6	96.5	56	30.5-4.0	1-1.2 1-1.5	1-2.0	23	66	26.0*1.6R	418gr
6	BUICK	APS C-26019/J	8N3184	HS475-814 D346	4	120.6	115	73.9-11.8 -7.1,-6.7	1-3.17 1-2.38	1-5.55	38.11	95.3	40.8*2.3 W	2.050