



# APS Automotive Enterprises Co.,Ltd.

A2,2ND Floor,Main Building,33 Changhong Road,Modern Logistics Park,Xiamen,China 361006

Tel: 86-592-5619 592 86-592-2620 070 Fax: 86-592-5610884 E-mail: aa@aaps.cn / karl@cps.cn

<http://www.apspart.com>

<http://apsparts.en.alibaba.com/index.html>

| NO. | CAR  | APS NO.   | OEM NO         | MODEL<br>&<br>DESCRIPTION | CYL<br>NO. | CYL.<br>DIA | PISTON |              |                 |     | PIN |      | CLIP       | N.W.<br>(KG) |
|-----|------|-----------|----------------|---------------------------|------------|-------------|--------|--------------|-----------------|-----|-----|------|------------|--------------|
|     |      |           |                |                           |            |             | LONG   | COMP<br>DIST | RING            |     | DIA | LONG |            |              |
|     |      |           |                |                           |            |             |        |              | COMP            | OIL |     |      |            |              |
| 1   | FUJI | APS 10601 |                | F-100 100cc               | 1          | 50.0        | 59.5   | 25.0+4.5     | 2-2.0           |     | 12  | 42.0 | 14<br>1.0R |              |
| 2   | FUJI | APS 10606 | 13100-114-0000 | 125cc                     | 1          | 55.0        | 68.37  | 33.0+3.37    | 2-1.5           |     | 14  | 44.0 | 16<br>1.2R |              |
| 3   | FUJI | APS 10651 | 217051-2-181   | 50cc                      | 1          | 40.0        | 46.5   | 24.3+3.0     | 1-1.0L<br>1-1.5 |     | 12  | 32.8 | 14<br>1.2R |              |