



APS Automotive Enterprises Co.,Ltd.

A2,2ND Floor,Main Building,33 Changhong Road,Modern Logistics Park,Xiamen,China 361006

Tel: 86-592-5619 592 86-592-2620 070 Fax: 86-592-5610884 E-mail: aa@aaps.cn / karl@cps.cn

<http://www.apspart.com>

<http://apsparts.en.alibaba.com/index.html>

NO.	CAR	APS NO.	OEM NO	MODEL & DESCRIPTION	CYL NO.	CYL. DIA	PISTON				PIN		CLIP	N.W. (KG)
							LONG	COMP DIST	RING		DIA	LONG		
									COMP	OIL				
1	IHC	APS F-31401	15612-023	Super A C123	4	85.7	90.5	49.3-8.0	3-2.38	1-4.76	21.8	70.0	25 1.6R	
2	IHC	APS F-31402	1099-023	SK287	4	82.6	92.0	47.7-5.0 -4.5	3-2.38	1-4.76	23.4	64.0	26 2.0R	
3	IHC	APS F-31403	1168-023	H	6	90.5	95.6	51.4-13.4-5.4 +6.3, +8.3	3-2.38	1-6.35	22.2	75.0	25 1.8R	
4	IHC	APS F-31404	SK368 1236-023	SK-271	4	87.3	107.5	63.2+7.3 +6.0, +0.3	3-2.38	1-4.76	28.2	70.5	31.5 2.0R	
5	IHC	APS F-31405	1139-023	SK-332 460-S60	4	104.8	129.7	78.8+7.3 +4.2, +0.7	3-2.38	1-6.35	33.4	82.0	37 2.2R	
6	IHC	APS F-31406	1150-023	300 350G	6	93.6	96.2	51.8-7.3 -0.9	1-3.17 1-3.17	1-6.35	28.6	80.0	31.5 1.2W	
7	IHC	APS F-31407	1137-023	666 766	4	92.1	107.8	63.4+3.2 -8.73	3-2.38	1-6.35	22.2	75.3	25 1.6R	
8	IHC	APS F-31408	1171-023	SK-262	6	95.25	98.5	51.5+2.8	1-3.17	1-6.35	22.225	75.3	25 1.6R	
9	IHC	APS F-31409	1066-023		4	101.6	130.2	79.3	3-2.38	1-6.35	33.35	82.0	37 2.2R	
10	IHC	APS F-31410	1148-023	330 340	6	90.4875	102.5	45.3+12.5 '+9.4, +0.5, -1.8	3-2.38	1-4.76	22.225	75.3	25 1.6R	
11	IHC	APS F-31411	1213-023	460GAS	4	82.55	88.6	41.2+3.3	2-2.38	1-4.76	21.825	70.0	25 1.6R	
12	IHC	APS F-31412	1147-023		6	90.4875	114.6	59.1+11.0 '+6.91	2-2.38	1-6.35	22.225	75.0	25 1.8R	
13	IHC	APS F-31413	12531-023 12549-023		4	106.3625	116.3	65.0+3.8 '+1.7, -2.7	3-2.38	2-6.35	31.75	82.5	34.4 1.2W	