



APS Automotive Enterprises Co.,Ltd.

A2,2ND Floor,Main Building,33 Changhong Road,Modern Logistics Park,Xiamen,China 361006

Tel: 86-592-5619 592 86-592-2620 070 Fax: 86-592-5610884 E-mail: aa@aaps.cn / karl@cps.cn

<http://www.apspart.com>

<http://apsparts.en.alibaba.com/index.html>

NO.	CAR	APS NO.	OEM NO	MODEL & DESCRIPTION	CYL NO.	CYL. DIA	PISTON				PIN		CLIP	N.W. (KG)
							LONG	COMP DIST	RING		DIA	LONG		
									COMP	OIL				
1	J.L.O	APS 50701		L-35	1	35	40.5	20.0+2.5	2-1.5		9	28.0	11 1.0R	0.04
2	J.L.O	APS T-50701		L35	1	35	40.5	20.0+2.5	2-1.5		9	28	10.7*1.0R	50gr
3	J.L.O	APS 50702		L-101 4HP	1	50	61.1	35.0+5.1	2-2.5		12	42.0	14 1.0R	0.105
4	J.L.O	APS 50703		L 155 6HP	1	59	69	39.0+5.0	3-2.5		14	50.0	16 1.0R	0.188
5	J.L.O	APS 50704		L-197	1	66	73.5	37.0+4.5	2-2.5		18	58.0	21 1.4R	0.197
6	J.L.O	APS 50705		L-252 8HP	1	69	84.75	50.0+4.75	3-2.5		16	57.0	18 1.0R	0.279
7	J.L.O	APS 50706	37505-805-01	L-252 8HP	1	69	84.5	49.5+5.0	3-2.5		16	57.0	18 1.0R	0.314
8	J.L.O	APS 50707		L-320 10HP	1	74	92	53.0+5.0	1-3.0K 2-2.5		20	64.0	23 1.4R	0.36
9	J.L.O	APS 50708		L-375 13.5HP	1	80	92.5	53.0+5.5	1-3.0K 2-2.5		20	70.0	23 1.4R	0.435
10	J.L.O	APS 50709		440/2	1	67.5	68	33.5+4.5	2-2.0K		16	51.0	17.3 1.0W	
11	J.L.O	APS 50709A			1	67.5	68	33.5+4.5	2-2.0K		16	51.0	18 1.2R	
12	J.L.O	APS 50710		L-77	1	43	59	31.0+4.0	2-2.0		12	36.0	14 1.0R	0.103
13	J.L.O	APS 50711		340/2	1	60	68	33.5+4.5	1-2.0K 1-2.0		16	51.0	17.3 1.0W	0.2
14	J.L.O	APS 50712		399/2	1	65	68	33.5+4.5	2-2.0		16	51.0	17.3 1.0W	0.25

15	J.L.O	APS 50713		L-80	1	43	40.8	21.8	2-1.5		9	28.0	11 1.0R	
----	-------	-----------	--	------	---	----	------	------	-------	--	---	------	------------	--