



# APS Automotive Enterprises Co.,Ltd.

A2,2ND Floor,Main Building,33 Changhong Road,Modern Logistics Park,Xiamen,China 361006

Tel: 86-592-5619 592 86-592-2620 070 Fax: 86-592-5610884 E-mail: aa@aaps.cn / karl@cps.cn

<http://www.apspart.com>

<http://apsparts.en.alibaba.com/index.html>

| NO. | CAR        | APS NO.     | OEM NO   | MODEL<br>&<br>DESCRIPTION | CYL<br>NO. | CYL.<br>DIA | PISTON |              |                 |        | PIN    |       | CLIP          | N.W.<br>(KG) |
|-----|------------|-------------|----------|---------------------------|------------|-------------|--------|--------------|-----------------|--------|--------|-------|---------------|--------------|
|     |            |             |          |                           |            |             | LONG   | COMP<br>DIST | RING            |        | DIA    | LONG  |               |              |
|     |            |             |          |                           |            |             |        |              | COMP            | OIL    |        |       |               |              |
| 1   | JOHN DEERE | APS F-29541 | 1182-023 |                           | 4          | 107.95      | 117.5  | 67.4-11.6    | 3-2.38          | 1-6.35 | 31.75  | 82.50 | 35.5*2.2R     |              |
| 2   | JOHNDEERE  | APS 30501/J |          | D6404                     | 4          | 108         | 124.5  | 70.0-19.3    | 1-3.0<br>1-2.38 | 1-4.76 | 38.1   | 85.0  | 40.8<br>1.5W  |              |
| 3   | JOHNDEERE  | APS 30502/J |          | D6406                     | 6          | 116         | 124.9  | 70.5-14.5    | 2-3.5           | 1-4.76 | 47.612 | 91.0  | 51.5<br>1.75W |              |