



APS Automotive Enterprises Co.,Ltd.

A2,2ND Floor,Main Building,33 Changhong Road,Modern Logistics Park,Xiamen,China 361006

Tel: 86-592-5619 592 86-592-2620 070 Fax: 86-592-5610884 E-mail: aa@aaps.cn / karl@cps.cn

<http://www.apspart.com>

<http://apsparts.en.alibaba.com/index.html>

NO.	CAR	APS NO.	OEM NO	MODEL & DESCRIPTION	CYL NO.	CYL. DIA	PISTON				PIN		CLIP	N.W. (KG)
							LONG	COMP DIST	RING		DIA	LONG		
									COMP	OIL				
1	KIA	APS F-20110JYH	OK4Y1-11-SAO	K3600	4	100.0	102.0	56.1-20.0 -0.1	2-2.0	1-3.0	34	82.0	36.5 1.5W	
2	KIA	APS T-20110YH/JYH			4	100	102	56.2-19.9 -0.1	2-2.0	1-3.0	34	82.0	36.5*1.5 W	
3	KIA	APS F-20112J	K4YO-11-SAO	JD K3500	4	100.0	105.0	58.0-18.0	1-2.5 1-2.0	1-4.5	34	82.0	36.5 1.5W	0.919
4	KIA	APS C-20113Y/JY		JT-FRONTIER 3.0	4	98	76	45.5-4.8 -1.5	2-2.0	1-3.0	30	79.0	32.1*1.2 W	0.760
5	KIA	APS F-20113JH		PREGIO 3.0	4	98.0	76.0	45.5-4.6 -2.0	2-2.0	1-3.0	30	79.0	32.1 1.2W	
6	KIA	APS T-20114	23411-3Y-300G	CANIVAL (NEW)	6	78.4	50.7	27.8	1-1.2 1-1.5	1-2.5	18	52.4	*	
7	KIA	APS T-20115	OK9YV-11-SAO-1	CANIVAL (OLD)	6	80.0	50.3	27.4	1-1.2 1-1.5	1-2.5	18	52.4	*	
8	KIA	APS F-20116J		K2700	4	92	103.4	60.4-5.8 -2.6	1-3.0 1-2.38	1-3.96	31.75	75.0	34.4 1.2W	
9	KIA	APS F-20117	23410-2Y010	1.8L	4	81	50.3	30.2-2.6	2-1.2	1-2.5	20	58.0	23 1.4R	
10	KIA	APS F-20117C		1.8L	4	81	50.3	29.9-2.6	2-1.2	1-2.5	20	58.0	23 1.4R	
11	KIA	APS T-20118		T3500-T	4	100	104.5	57.7-18.4	1-2.5 1-2.0	1-4.5	34	82.0	36.5 1.5W	
12	KIA	APS F-20119JY	OK5Z1-11-SAO	2.9L	4	97.1	84	52.0-17.8	1-2.0 1-2.0	1-3.0	32	78.0	34.4*1.2 W	
13	KIA	APS F-20124/J		K3000	4	95	115.5	58.45-4.7 -2.1	2-2.5	1-4.0	31.79	75.0	34.4*1.2 W	
14	KIA	APS C-20303/J		DM100	6	90	104	53.8-4.4 -1.9	3-2.5	2-4.0	29	77.0	31.1*1.2 W	

15	K/A	APS C-20126Y/JY		H100	4	124	128.5	80.4-27.5	1-3.0 1-2.5	1-4.0	46	98.6	49.5*2.0 W	
16	K/A	APS C-20127Y/JY			4	98	90.3	48.3-2.6 -1.5	1-2.5 1-2.0	1-3.0	30	79.0	32.1*1.2 W	