



# APS Automotive Enterprises Co.,Ltd.

A2,2ND Floor,Main Building,33 Changhong Road,Modern Logistics Park,Xiamen,China 361006

Tel: 86-592-5619 592 86-592-2620 070 Fax: 86-592-5610884 E-mail: aa@aaps.cn / karl@aaps.cn

<http://www.apspart.com>

<http://apsparts.en.alibaba.com/index.html>

| NO. | CAR     | APS NO.      | OEM NO | MODEL<br>&<br>DESCRIPTION | CYL<br>NO. | CYL.<br>DIA | PISTON |                |       |       | PIN  |      | CLIP         | N.W.<br>(KG) |
|-----|---------|--------------|--------|---------------------------|------------|-------------|--------|----------------|-------|-------|------|------|--------------|--------------|
|     |         |              |        |                           |            |             | LONG   | COMP<br>DIST   | RING  |       | DIA  | LONG |              |              |
|     |         |              |        |                           |            |             |        |                | COMP  | OIL   |      |      |              |              |
| 1   | PORSCHE | APS 30401    |        |                           | 4          | 86          | 69.7   | 27+4.4<br>-1.8 | 3-2.0 | 1-5.0 | 22   | 68.5 | 23.5<br>1.0W | 0.358        |
| 2   | PORSCHE | APS F-30401U |        |                           | 4          | 86          | 69.7   | 27+4.4         | 3-2.0 | 1-5.0 | 22   | 68.5 | 23.5<br>1.0W | 0.358        |
| 3   | PORSCHE | APS 30402    |        |                           | 4          | 86          | 63.5   | 27+4.6         | 2-1.5 | 1-4.0 | 22   | 63.0 | 23.5<br>1.0W | 0.332        |
| 4   | PORSCHE | APS F-30403  |        |                           | 6          | 084         | 77.0   | 34.2+7.0       | 2-1.5 | 1-4.0 | 22.0 | 66.0 | 25<br>1.6R   |              |
| 5   | PORSCHE | APS C-30403H |        |                           | 6          | 86          | 83     | 34.2+13.0      | 2-1.5 | 1-4.0 | 22   | 66   | 23.5*1.0W    |              |